These measurements refer to the frame work and do not include upholstery, seam or zip

k	Tolerances (mm)			
	Dimension			Deviation
	(1)	-	20	±0,2
	(20)	-	50	±0,5
	(50)	-	200	±1,0
	(200)	-		±2,0





